



MAP EXPLANATION

-  Fault or lineament of Knuepfer (1977) - Solid line indicates well-defined photogeologic lineament or well-defined surficial evidence of faulting; dashed line poorly-defined photogeologic lineament or ambiguous surficial evidence of faulting; (nature of lineament uncertain); dotted line is inferred extension of fault where concealed by recent sediments.
-  Scarp Annotations by Knuepfer (1977)
-  saddle Annotations by Bryant (this report). Underline in green, rather than box, indicates response or modification to observations of Knuepfer (1977).
-  Attitude of bedding from Sims, et al (1973).

Figure 4b (to FER-136). Cannon Hills segment (southern section) of the Vaca-Montezuma Hills fault zone. 136-3